

# EPA Notification of Hazardous Waste Site

United States  
Environmental Protection  
Agency  
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

ORIGINAL R

810609

WV 69  
1115 000 001 074

## Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name Monsanto Company  
Street N/A  
City Nitro State WV Zip Code 25143

## Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Monsanto's Present Landfill  
Street Route 25  
City Nitro County Putnam State WV Zip Code 25143

## Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Galloway, H. M.  
Supt., EHS&PA  
Phone (304) 755-3341

## Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1964 To (Year) Present 1981

WVD 98 053 7765

## E Waste Type: Choose the option you prefer to complete.

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:  
Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

- Mr.
- ☒ 1. Organics
  - ☒ 2. Inorganics
  - ☐ 3. Solvents
  - ☐ 4. Pesticides
  - ☐ 5. Heavy metals
  - ☐ 6. Acids
  - ☐ 7. Bases
  - ☐ 8. PCBs
  - ☒ 9. Mixed Municipal Waste
  - ☐ 10. Unknown
  - ☐ 11. Other (Specify)

Source of Waste:  
Place an X in the appropriate boxes.

- ☐ 1. Mining
- ☐ 2. Construction
- ☐ 3. Textiles
- ☐ 4. Fertilizer
- ☐ 5. Paper/Printing
- ☐ 6. Leather Tanning
- ☒ 7. Iron/Steel Foundry
- ☒ 8. Chemical, General
- ☐ 9. Plating/Polishing
- ☐ 10. Military/Ammunition
- ☐ 11. Electrical Conductors
- ☐ 12. Transformers
- ☐ 13. Utility Companies
- ☐ 14. Sanitary/Refuse
- ☐ 15. Photofinish
- ☐ 16. Lab/Hospital
- ☐ 17. Unknown
- ☐ 18. Other (Specify)

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:  
EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.


RECEIVED  
RCRA SECTION  
EPA REGION III  
JUN 9 1981

**F Waste Quantity:**  
Place an X in the appropriate boxes to indicate the facility types found at the site.  
In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.  
In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

**Facility Type**

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☒ Drums, Below Ground
9. ☐ Other (Specify) \_\_\_\_\_

**Total Facility Waste Amount** 4000000  
See Item I cubic feet 4.25 X 10<sup>6</sup> cu. ft.  
gallons  
**Total Facility Area**  
square feet  
acres 34 A

**ORIGINAL**  
(D-4)

**G Known, Suspected or Likely Releases to the Environment:**  
Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☒ None

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

**H Sketch Map of Site Location: (Optional)**  
Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

Y See attached map.

**I Description of Site: (Optional)**

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

There are no records or data on the amounts or type of wastes disposed of at this site by Monsanto. Waste material that was known to be toxic at the time was not taken to this facility. Plant trash and waste that were taken to this site were buried. Hazardous waste volumes as given are based on current ratios of hazardous waste to production. This ratio is applied to estimates of production at the time the site was used for disposal.

**J Signature and Title:**

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name D. S. Frazer, Plant Manager

Street \_\_\_\_\_

City Nitro

State WV Zip Code 25143

Signature R. L. Sparks for  
D. S. Frazer

Date 6/9/81

- ☒ Owner, Present  
☐ Owner, Past  
☐ Transporter  
☐ Operator, Present  
☐ Operator, Past  
☐ Other

WVS-000-001-074

ENVIRONMENTAL PROTECTION AGENCY  
NOTIS DATA MANAGEMENT SYSTEM  
COMMENT MAINTENANCE FORM


[illegible]

CARD																COMMENT		
CODE NTS IDENTIFICATION NO.																		
F																WST VOL. BASED ON CURRENT RATIOS		
C																002		
1	2															55	56	58


CARD CODE NTS IDENTIFICATION NO. HAZARDOUS LIST TO PRODUCTION COMMENT 003

CARD CODE NTS IDENTIFICATION NO.	
F C	S
1 2 13 14 15 16	55 56 58

[illegible]



SCALE 1:24,000



CONTOUR INTERVAL 20 FEET  
DOTTED LINES REPRESENT 10-FOOT CONTOURS


ROAD CLASSIFICATION	
Heavy-duty	Light-duty
Medium-duty	Unimproved dirt
Interstate Route	U.S. Route
	State Route



SAINT ALBANS, W. VA.  
N 3622.5—W 8145/7.5

1958  
PHOTOREVISED 1971

ORIGINAL



# Monsanto

Monsanto Company  
Nitro, West Virginia 25143

TO

U.S. EPA REGION 3  
Site Notification  
Philadelphia, PA 19106

RECEIVED

CERTIFIED

**Monsanto**

RECEIVED  
RCRA SECTION  
EPA REGION III

JUN 9 1981

MONSANTO INDUSTRIAL CHEMICALS CO.  
Nitro, West Virginia 25143  
Phone: (304) 755-3341

June 9, 1981

U.S. EPA Region 3  
Sites Notification  
Philadelphia, PA 19106

Dear Sir:

Please find enclosed the Nitro Plant Notification of Hazardous Waste Sites Form #8900-1. If you should have any questions or comments please feel free to contact me at your convenience.

*K.S. Miller*

K. S. Miller

rh

Enclosure

RECEIVED

JUN 12 1981

PERMITS ENFORCEMENT BRANCH